EXAMINER AMENDMENT Notice of Allowability

Application No.	Applicant(s)	
10/771,945	KOVACS, GEORGE	
Examiner	Art Unit	
Michael C. Zarroli	2839	

e. THIS ne initiative
om the
nents
E OF
) of he
) e

NICHAEL C. ZAPROLI PRIMARY EXAMINER

Michael C. Zand

EXAMINER'S AMENDMENT

1. An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Paul Fattibene on 12/20/04.

The application has been amended as follows: Revise claims 1 and 17 as shown on the attached sheets. Also, revise the abstract as shown on the attached sheet.

- 2. The following changes to the drawings have been approved by the examiner and agreed upon by applicant: The drawings appear informal mostly because some of the numerals are hard to read. Examiner recommends numerals **not** be written in by hand. In order to avoid abandonment of the application, applicant must make these above agreed upon drawing changes.
- 3. The following is an examiner's statement of reasons for allowance: The combinations in claims 1, 12 and, 15 especially the socket opening that receives

Application/Control Number: 10/771,945

Art Unit: 2839

the bridge. Also in these claims, the locking land in the socket that extends into the gap. Regarding claim 17, a gap between the lamp base and bridge and a portion of the socket can extend into the gap.

Page 3

Any comments considered necessary by applicant must be submitted no later than the payment of the issue fee and, to avoid processing delays, should preferably accompany the issue fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for Allowance."

4. The prior art made of record and not relied upon is considered pertinent to applicant's disclosure. Howard teaches a lamp base and pins but no bridge between the pins. Sambonet teaches a bridge and socket but no gap between the bridge and lamp base. Garver teaches pins and socket but once again no gap between a bridge and lamp surface. Nagase et al teaches a socket that receives a lamp but no gap between a bridge and lamp surface. Chang teaches a socket, pins and lamp base but no gap between bridge and base that receives a portion of the socket. Tseng teaches a gap between a bridge and lamp base but no portion of the socket extends into the gap.

Application/Control Number: 10/771,945 Page 4

Art Unit: 2839

5. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Michael C. Zarroli whose telephone number is 571-272-2101. The examiner can normally be reached on 7:30 to 3:30 M-F.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, T.C. Patel can be reached on (571) 272-2800 ext 39. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Michael C. Zarroli Primary Examiner Art Unit 2839

MCZ MCZ